

# Product Change Notification

## 2" Hub/Disk Assembly Screw Change

PCN-6644

Date of Notification	Change		Part Numbers Affected
September 26, 2018	<input type="checkbox"/> Major	<input checked="" type="checkbox"/> Minor	HUBDISK-2, E3, E6

### Notification

<input type="checkbox"/> Product Obsolescence	<input type="checkbox"/> Product Marking	<input type="checkbox"/> Process Change	<input type="checkbox"/> Design Change
<input checked="" type="checkbox"/> Material Change	<input type="checkbox"/> Specification Change	<input type="checkbox"/> Component Change	<input type="checkbox"/> Other

### Notification Description (Including Extent, Purpose / Reason, and Effect on Form, Fit and Function)

As part of our ongoing continuous improvement efforts, the screws used in the assembly of the 2" hub/disk assembly, that is with a bore of 12mm and larger, will be changed from a black oxide to a zinc plated screw. The zinc plating improves corrosion resistance as well as alleviates any potential for oil residue. The plating change has no effect on form, fit or function of our hubdisk assembly.



If you have any questions or concerns about this PCN, please contact our Technical Support Group at 360-397-9999 or email [support@usdigital.com](mailto:support@usdigital.com).



[usdigital.com](http://usdigital.com)  
1400 NE 136th Ave.  
Vancouver, WA 98684  
Local: 360.260.2468  
Sales: 800.736.0194

# Product Change Notification

## 2" Hub/Disk Assembly Screw Change

PCN-6644

### Alternate Parts (as applicable)

N/A

### Effective Date (Including Last Time Buy Date and Conditions, as applicable)

Effective immediately